

Butt Connectors

Butt Splices Take Two Crimps, One Over Each Wire
Provide Insulation From Wire To Wire



NYLON INSULATED BUTTED SEAM BARREL



VINYL INSULATED BUTTED SEAM BARREL



VINYL FLARE INSULATED BUTTED SEAM BARREL



NON-INSULATED BUTTED SEAM BARREL



NYLON INSULATED SOLID BARREL

Red 22-16 AWG				Blue 16-14 AWG				Yellow 12-10 AWG			
Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty
1100A	1000	1100G	100	1200A	1000	1200G	100	1300A	500	1300G	100
1100C	50	1100PT	50	1200C	50	1200PT	50	1300C	25	1300PT	25
1100D	11	1100KT	11	1200D	11	1200KT	11	1300D	6	1300KT	6
1100M	4	1100QT	4	1200M	4	1200QT	4	1300M	2	1300QT	2
1400A	1000	—	—	1500A	1000	—	—	1600A	500	—	—
1400C	50	1400PT	50	1500C	50	1500PT	50	1600C	25	1600PT	25
1400D	10	1400KT	10	1500D	10	1500KT	10	1600D	6	1600KT	6
1700A	1000	1700G	100	1800A	1000	1800G	100	1900A	500	1900G	100
1700C	50	1700PT	50	1800C	50	1800PT	50	1900C	25	1900PT	25
1700H	20	1700KT	20	1800H	20	1800KT	20	1900H	14	1900KT	14
1700D	12	—	—	1800D	12	—	—	1900D	8	—	—
1700M	5	1700QT	5	1800M	5	1800QT	5	1900M	4	1900QT	4
2300A	1000	—	—	2400A	1000	—	—	2500A	500	—	—
2300C	100	—	—	2400C	100	—	—	2500C	50	—	—
2000A	1000	—	—	2100A	1000	—	—	2200A	500	—	—
2000C	50	2000PT	50	2100C	50	2100PT	50	2200C	25	2200PT	25

Step Down Butt Connectors

Vinyl Flare Insulated
Step Down End Color Coded With Colored Strip
For Smaller Wire Gauge



Color	Gauge	Part #	Qty	Part #	Qty
Blue w/Red Stripe	16-14 to	2280A	100	—	—
	22-18	2280C	25	2280PT	25
Yellow w/Blue Stripe	12-10 to	2285A	100	—	—
	16-14	2285C	25	2285PT	25
Red w/Yellow Stripe	8 to	2286A	100	—	—
	12-10	2286C	15	2286PT	15
Blue w/Red Stripe	6 to	2287A	100	—	—
	8	2287C	10	2287PT	10



HEAT SHRINK STEP DOWN BUTT CONNECTORS

Step Down Butt Connectors
Crimp & Heat Shrink Connectors
With Adhesive Lined Heat Shrink Tubing
Operating Temperature -67°F to 230°F



Color	Gauge	Part #	Qty	Part #	Qty
Blue w/Red Stripe	16-14 to 22-16	2265A	100	—	—
		2265G	25	2265GT	25
		2265C	5	2265PT	5
Yellow w/Blue Stripe	12-10 to 16-14	2275A	100	—	—
		2275G	25	2275GT	25
		2275C	5	2275PT	5
Red w/Yellow Stripe	8 to 12-10	2295A	100	—	—
		2295G	25	2295GT	25
		2295C	5	2295PT	5

Parallel Connectors

Stripped Wires Overlap Inside Connector
Requires Only One Crimp In Center



VINYL FLARE INSULATED BUTTED SEAM BARREL



NYLON INSULATED SOLID BARREL

Red 22-16 AWG		Blue 16-14 AWG		Yellow 12-10 AWG	
Part #	Qty	Part #	Qty	Part #	Qty
1701A	1000	1801A	1000	1901A	500
1701C	100	1801C	100	1901C	50
1701D	11	1801D	11	1901D	7
1701PT	100	1801PT	100	1901PT	50
2001A	1000	2101A	1000	2201A	500
2001C	100	2101C	100	2201C	50
2001PT	100	2101PT	100	2201PT	50

Closed End Connectors

Flared Nylon Cap
Electro-Tin Plated Copper Insert
Terminates Groups of 2-4 Wires
Insert Stripped Wires Into Connector Insert
& Crimp On Insert



22-14 AWG		16-10 AWG		8 AWG	
Part #	Qty	Part #	Qty	Part #	Qty
1266A	1000	1366A	500	4066A	250
1266C	50	1366C	25	4066C	20
1266H	14	1366D	9	4066KT	1
1266D	10	1366M	3	—	—
1266M	4	1366PT	25	—	—
1266PT	50	1366QT	3	—	—
1266QT	4	—	—	—	—

Wire Nuts

Screw Wire Nuts Onto Ends of Stripped Wires
Terminates Groups of Two to Four Wires



Color	Gauge	Part #	Qty	Part #	Qty	Part #	Qty
Ivory	Min 2 #18 Ga Max 2 #16 Ga	1545A	1000	1545H	20	1545PT	50
		1545C	50	1545D	15	1545KT	20
		—	—	1545M	6	1545QT	6
Blue	Min 3 #22 Ga Max 3 #16 Ga	1544A	500	1544D	13	1544PT	25
		1544C	25	1544M	5	1544KT	15
		—	—	—	—	1544QT	5
Yellow	Min 4 #18 Ga Max 2 #12 Ga	1546A	250	1546H	10	1546PT	15
		1546C	15	1546D	7	1546KT	10
		—	—	1546M	3	1546QT	3

All Items with QT, KT or PT Suffix are Clam Shell Program Items.