

# Butt Connectors

Heat Shrink Butts Page 8

Butt Splices Take Two Crimps, One Over Each Wire  
Permanently Joins Two Wires Providing Insulation From Wire To Wire

**NYLON INSULATED BUTTED SEAM BARREL**



**VINYL INSULATED BUTTED SEAM BARREL**



**VINYL FLARE INSULATED BUTTED SEAM BARREL**



**NON-INSULATED BUTTED SEAM BARREL**



**NYLON INSULATED SOLID BARREL**



**NON-INSULATED SOLID BARREL**



Red 22-16 AWG				Blue 16-14 AWG				Yellow 12-10 AWG			
Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty	Part #	Qty
1100A	1000	—	—	1200A	1000	—	—	1300A	500	—	—
1100G	100	—	—	1200G	100	—	—	1300G	100	—	—
1100C	50	1100PT	50	1200C	50	1200PT	50	1300C	25	1300PT	25
1100D	11	1100KT	11	1200D	11	1200KT	11	1300D	6	1300KT	6
1100M	4	1100QT	4	1200M	4	1200QT	4	1300M	2	1300QT	2
1400A	1000	—	—	1500A	1000	—	—	1600A	500	—	—
1400C	50	1400PT	50	1500C	50	1500PT	50	1600C	25	1600PT	25
1400D	10	1400KT	10	1500D	10	1500KT	10	1600D	6	1600KT	6
1700A	1000	—	—	1800A	1000	—	—	1900A	500	—	—
1700G	100	—	—	1800G	100	—	—	1900G	100	—	—
1700C	50	1700PT	50	1800C	50	1800PT	50	1900C	25	1900PT	25
1700H	20	1700KT	20	1800H	20	1800KT	20	1900H	14	1900KT	14
1700D	12	—	—	1800D	12	—	—	1900D	8	—	—
1700M	5	1700QT	5	1800M	5	1800QT	5	1900M	4	1900QT	4
2300A	1000	—	—	2400A	1000	—	—	2500A	500	—	—
2300C	100	—	—	2400C	100	—	—	2500C	50	—	—
2000A	1000	—	—	2100A	1000	—	—	2200A	500	—	—
2000C	50	2000PT	50	2100C	50	2100PT	50	2200C	25	2200PT	25
<b>26-24 AWG</b>											
2360A	1000	—	—	—	—	—	—	—	—	—	—
2360C	100	—	—	—	—	—	—	—	—	—	—

# Step-Down Butt Connectors

Tin Plated Copper Connectors  
Used to Join Two Wires of Two Different Wire Gauges

**VINYL FLARE INSULATED**



Color Coded Stripes Denote Wire Gauge  
Red Stripe: 22-16 AWG (or 8 GA)  
Blue Stripe: 16-14 AWG  
Yellow Stripe: 12-10 AWG

Color	Gauge	Part #	Qty	Part #	Qty
Blue w/Red Stripe	16-14 to	2280A	100	—	—
	22-18	2280C	25	2280PT	25
Yellow w/Blue Stripe	12-10 to	2285A	100	—	—
	16-14	2285C	25	2285PT	25
Red w/Yellow Stripe	8 to	2286A	100	—	—
	12-10	2286C	15	2286PT	15
Blue w/Red Stripe	6 to	2287A	100	—	—
	8	2287C	10	2287PT	10

## HEAT SHRINK STEP-DOWN BUTT CONNECTORS

Crimp & Heat Shrink Connectors  
Adhesive Lined Heat Shrink Tubing  
Operating Temperature -67°F to 230°F (-55°C to 110°C)



Color	Gauge	Part #	Qty	Part #	Qty
Blue w/Red Stripe	16-14 to 22-16	2265AA	1000	2265A	100
		2265G	25	2265GT	25
		2265C	5	2265PT	5
Yellow w/Blue Stripe	12-10 to 16-14	2275AA	1000	2275A	100
		2275G	25	2275GT	25
		2275C	5	2275PT	5
Red w/Yellow Stripe	8 to 12-10	2295AA	500	2295A	100
		2295G	25	2295GT	25
		2295C	3	2295PT	3

# Parallel Connectors

Parallel Splice Connectors Provide Insulated Connection From Wire To Wire With A Single Crimp

**VINYL FLARE INSULATED BUTTED SEAM BARREL**

Stripped Wires Intermingle & Overlap Inside Connector  
Requires Only One Crimp In Center



**NYLON INSULATED SOLID BARREL**



Red 22-16 AWG		Blue 16-14 AWG		Yellow 12-10 AWG	
Part #	Qty	Part #	Qty	Part #	Qty
1701A	1000	1801A	1000	1901A	500
1701C	100	1801C	100	1901C	50
1701D	11	1801D	11	1901D	7
1701PT	100	1801PT	100	1901PT	50
2001A	1000	2101A	1000	2201A	500
2001C	100	2101C	100	2201C	50
2001PT	100	2101PT	100	2201PT	50

All Items with QT, KT, ET, GT or PT Suffix are Clam Shell Program Items.